## Superbase<sup>®</sup> Blend Sheet

## 610

Super Stripper (2900 Version)

Date: \_\_\_\_\_

Batch Number:\_\_\_\_\_

Yield: 165 Gallons (624 Liters)

Essential Batch Number:\_\_\_\_\_

- **1.** Make sure blending tanks and equipment are clean.
- **2.** Pump 106 gallons (397 liters) of water into mixing tank.
- **3.** While agitating, add 45 lbs. (20 kgs.) of Powdered Additive 941. Agitate until thoroughly dissolved.
- 4. Add 55 gallons (208 liters) of SUPERBASE 610.
- **5.** While agitating, add 5 gallons (19 liters) of 2200 Coupling Agent.
- **6.** Agitate for (5) minutes. Batch complete.
- 7. Package in clean plastic drums and containers.

Note: One drum of 610 makes 165 gallons of 2900.

SDS and label copy for finished product may be obtained from Essential Industries at (800)-551-9679 or (262) 538-1122.

## CONFIDENTIAL