

2224

Glass & Surface Cleaner

(Concentrated Version)

Date: _____

Batch Number: _____

Yield: **15 Gallons (57 Liters)**

Essential Batch Number: _____

-
1. Make sure blending tanks and equipment are clean.
 2. Pump 10 gallons (38 liters) of water into mixing tank. Begin to agitate.
 3. Add 5 gallons (19 liters) of SUPERBASE 2224.
 4. Continue agitating for five (5) minutes for thorough blending. Batch complete.
 5. Package in clean plastic containers.

SDS and label copy for finished product may be obtained from
Essential Industries at (800)-551-9679 or (262) 538-1122.