Floor Care Maintenance



WEEKLY BURNISH SYSTEM

DAILY MAINTENANCE



The first step in all floor maintenance operations is dust mopping.

Start by scraping up any chewing gum or attached labels with a long-handled or razor scraper. Sweep around all hard-to-reach areas.

Using a clean dust mop, sweep all loose soil into main aisle and consolidate for immediate disposal.



All spills or tracked-in soil should be spot mopped immediately. Use a 2 oz. per gallon solution of neutral cleaner.*

* $\ensuremath{\mathcal{V}}_2$ oz./gal. with Neutral Cleaner Super Concentrate.



Autoscrub the floor with red pads and a 2 oz./gal.* dilution of Neutral Cleaner. Pick up the trail left by the autoscrubber with a mop and bucket of clean, cold water.

For areas that are damp mopped, use a clean mop and a 2 oz./gal.* solution of Neutral Cleaner.

* $\frac{1}{2}$ oz./gal. with Neutral Cleaner Super Concentrate.

WEEKLY RESTORATION



Weekly restoration keeps floors looking their best.

Start by scraping up any chewing gum or attached labels with a long-handled or razor scraper. Sweep around all hard-to-reach areas.

Using a clean dust mop, sweep all loose soil into main aisle and consolidate for immediate disposal.



Auto scrub with red pads and a 2 oz./gal.* solution of Floor Cleaner & Restorer. Pick up the trail left by the scrubber with a mop and clean, cold water.

For facilities without a scrubber use a clean mop and bucket with a 2 oz./gal.* solution of Floor Cleaner & Restorer. Allow floor to dry before buffing.

* $\frac{1}{2}$ oz./gal. Floor Cleaner & Restorer Super Concentrate.



Buff the entire facility using a high speed machine and buffing pads. Turn pads often to prevent pad loading. Always dust mop after buffing.

PERIODIC SCRUB AND RECOAT



When floors won't respond to their original high gloss look with restoration, it's time to recoat.

Start by scraping up any chewing gum or attached labels with a long-handled or razor scraper. Sweep around all hard-to-reach areas.

Using a clean dust mop, sweep all loose soil into main aisle and consolidate for immediate disposal.



Scrub the floor with scrub pads and an 8 oz. per gallon solution of floor cleaner & restorer.* Make sure vacuum is on and squeegees are down while applying solution. Rinse the floor immediately and allow it to dry thoroughly.

* 2 oz./gal. Floor Cleaner & Restorer Super Concentrate.



Using a clean finish mop and a bucket with a plastic liner, apply a coat of floor finish, staying at least 6" away from the edges. Always apply finish in thin, even coats.

If applying more than one coat of floor finish, allow at least 30 minutes dry time between coats.



Essential Industries, Inc. κ0123 Merton, Wisconsin 53056 (262) 538-1122 or 800.551.9679

www.essind.com