



Carefully remove gum, tape and labels with a putty knife. Angle the blade so you don't damage the finish.



Using a clean dust mop, sweep all loose soil and consolidate for immediate disposal.

Apply

Finish



Working in 200 ft² sections, strip existing finish and rinse using a 2 oz./gal. dilution of Blue Concentrate (2085FC). *If floor is unfinished, skip to step 4.



Apply an 8 oz./gal. dilution of Blue Concentrate (2085FC) in 200 ft² sections. (Use a KaiMotion, mop and bucket or an auto scrubber.)



Auto scrub with maroon pads, picking up solution before moving to next section. Floor should be uniformly clean and mark-free. Using a clean microfiber finish mop and a KaiMotion bucket or pour can, apply 4 coats of Pantheon (273CF) per label instructions, staying at least 6" away from the edges.



When the finish has dried, buff the floor using a burnisher fitted with a white pad to "force cure" the floor and maximize the gloss.

ESSENTIAL® INDUSTRIES

P.O. Box 12 | Merton, Wisconsin 53056 262.538.1122 or 800.551.9679

www.essind.com

©2021 Essential Industries, Inc. D1221